



“Maunawili”

Underwater Propeller Inspection

**Berth C62
Long Beach Harbor, California**

April 20, 2015

Matson Navigation Company
1521 Pier C Street
Long Beach, CA 90813



MULDOON MARINE SERVICES, INC.
P.O. Box 7457 Long Beach, CA 90807
Tel +1 562 432-5670 Fax +1 562 432-6623
mmsi@muldoonmarine.com

UNDERWATER SERVICE REPORT

GENERAL DETAILS

Vessel: "Maunawili" Date: April 20, 2015
Location: Long Beach, CA Berth C62 Draft: Aft: 7M
Sea State: Calm Visibility: 10' Current: -0-

UNDERWATER ASSIGNMENT

Hull Cleaning: Yes No Propeller Polishing: Yes No
Others: Class IWS/CCTV Visual Survey With Photos Others/Repair

PROPELLER

No. Of Blades: 6

Type: Single Twin

UNDERWATER SERVICE REPORT:

PROPELLER

Blade Condition Good Fair Poor
Bolting Assembly Intact Yes No Na

DESCRIPTION

Pittings	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	
Cavitation / Erosion	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	
Tears	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	
Cracks	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	
Deflection/ Scouring	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	
Previous Repairs	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	
Any Oil Leaking From Blade Seal	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Na <input type="checkbox"/>

Remarks:

The propeller is coated with Coverall clear coating.

Minor cavitation was observed on the 0.9 radius near the tips of all six blades, this cavitation was coated during the last dry docking. The coating on and around the areas of cavitation did not appear to be damaged. However, it was very difficult to determine the coating condition on cavitated areas due to the difference in texture caused by the cavitation.

The previous grinding repair observed on blade D was still holding. The repair was coated over and both the coating are repair were in good condition.

All blades are fouled with light slime on leading and trailing edge. Sporadic tube worms were observed on the pressure face and suction back. The diver wiped the inner radii of the propeller surfaces clean in order to allow us to have an accurate measure of fouling.

Overall surface roughness appears to be a "B". The clear coating changes the appearance of the propeller surface and makes it smoother to the touch than an uncoated propeller. Due to this fact the surface does not correlate exactly with the facsimile representations on the Rubert Propeller Roughness Gauge.

Some areas near the .4 radius appeared to have been missed during the coating process; these uncoated areas were approximately two grades rougher than the coated surfaces. See photos page M and N.



FAIR WATER CAP

Condition	Good	<input checked="" type="checkbox"/>	Defective	<input type="checkbox"/>		
Cement Covers	Intact	<input type="checkbox"/>	Missing	<input type="checkbox"/>	Na	<input checked="" type="checkbox"/>
Bolting Assembly	Intact	<input checked="" type="checkbox"/>	Missing	<input type="checkbox"/>	Covered	<input type="checkbox"/>

PROPELLER SHAFT

Any Oil Leaking From Shaft	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
Any Damage To Tailshaft Assembly	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
Any Entanglement On Shaft	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
If Yes, Has It Been Removed	Yes	<input type="checkbox"/>	No	<input type="checkbox"/>

PROPELLER CONDITION REMARKS

Blade #A: Cavitation on .9 radius 2.5 inches in length, see photos pages B and C. Coating is in good condition.

Blade #B: Cavitation on .9 radius 2 inches in length, see photos page D. Coating is in good condition.

Blade #C: Cavitation on .9 radius 1.5 inches in length, page F and G. Coating is in good condition.


Blade #D: Cavitation on .9 radius 2 inches in length, see photos pages H and I. Coating is in good shape. A previous grinding repair was observed was still holding, see photos page I. The repair was coated over.

Blade #E: Cavitation on .9 radius 4 inches in length, See photos page K. Coating is in good shape.

Blade #F: Cavitation on .9 radius 3.5 inches in length, see photo page M. Coating is in good shape.

See diagram page 5

PROPELLER DIAGRAM SHEET



ROPE GUARD COVER

Condition Good Defective

Type Welded Bolted Access Hole Top Bottom

Are Cutters Intact Yes No Na

Erosion/ Corrosion Yes No

RUDDER

Rudder Horn Any Visible Damage Yes No

Rudder Stock Any Visible Damage Yes No

Plate Condition Good Satisfactory Poor Damage

Any Visible Cracks Yes / Indicated In Drawing No

Rudder Plug Nos.: 1___ Intact Not Intact

Rudder Pintle Clearance Taken Yes No Na


Remarks: Previous repair observed on rudder flat bottom by leading edge. Repair is in good condition. One anode was missing and the remaining anodes are 40% wasted.



Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade A: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade A: Cavitation on .9 radius 2.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade A: Cavitation on .9 radius 2.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.




Blade A: Cavitation on .9 radius 2.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade A: Cavitation on .9 radius 2.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade B: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade B: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.




Blade B: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade C: Cavitation at the .9 radius, 1.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade C: Cavitation at the .9 radius, 1.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade C: Cavitation at the .9 radius, 1.5 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade D: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade D: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade D: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade D: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.




Blade D: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.




Blade D: Cavitation at the .9 radius, 2 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade D: A previous grinding repair was observed was still holding.



Blade D: A previous grinding repair was observed was still holding.



Blade D: A previous grinding repair was observed was still holding.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade E: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade E: Cavitation at the .9 radius, 4 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade E: Cavitation at the .9 radius, 4 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade E: Cavitation at the .9 radius, 4 inches in length. Surfaces around the cavitation damage appeared to still have intact coating.



Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.



Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade F: fouled with light slime on leading and trailing edge. Tube worms were observed on the pressure face and suction back. Coating in good condition overall.




Blade F: Cavitation at the .9 radius, 3.5 inches in length.



A removable plug on the propeller was intact. Minor coating loss around the plug.




Some areas near the .4 radius appeared to have been missed during the coating process; these uncoated areas were approximately two grades rougher than the coated surfaces.



Some areas near the .4 radius appeared to have been missed during the coating process; these uncoated areas were approximately two grades rougher than the coated surfaces.



Some areas near the .4 radius appeared to have been missed during the coating process; these uncoated areas were approximately two grades rougher than the coated surfaces.



Some areas near the .4 radius appeared to have been missed during the coating process; these uncoated areas were approximately two grades rougher than the coated surfaces.