

CALIFORNIA COASTAL COMMISSION

South Coast District Office
301 Ocean Blvd., Suite 300
Long Beach, CA 90802
(562) 590-5071



W12c

(CDP 5-20-0006, Marquita LLC and City of San Clemente)

OCTOBER 7, 2020

REVISED EXHIBITS

Exhibits 4, 5, 7,8, and 9 added on 9/30/20,

no change to Exhibits 1, 2, 3, 6, 10, 11, or 12

Table of Contents

Exhibit 1 – Vicinity Map

Exhibit 2 – 2015 Topographic Survey

Exhibit 3 – Figures Depicting Bluff Slide

Exhibit 4 – Site Photos

Exhibit 5 – Unpermitted Development at the Bluff Toe

Exhibit 6 – Bluff Rough Grading Plan/Geologic Cross Sections

Exhibit 7 – Bluff Repair Plan (Reinforced Fill and Geogrid)

Exhibit 8 – Construction Phase Erosion Control and Staging Plans

Exhibit 9 – Bluff Revegetation/Habitat Restoration Plan

Exhibit 10 – Architectural Plans for Residential Development

Exhibit 11 – Grading/Drainage Plans for Residential Development

Exhibit 12 – Revised Bluff Setback







9/24/2020, 3:24:16 PM


-  City Boundary
-  Green: Band_2
-  Outside City Mask
-  Blue: Band_3

Eagle 1ft Tiled 2019

-  Red: Band_1



Source: Esri, Maxar, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community, Esri, HERE, Garmin, (c) OpenStreetMap contributors, and the GIS user community, Eagle Aerial



RECORDING NOTE:
RECORDING NO. 15523
ELEVATION 100.00
DATE 08/01/2015, 2005 A.O.L.

EXEMPT NOTE: THIS SURVEY WAS PREPARED WITHOUT A TITLE REPORT.
UNLITTED EXEMPTS MAY EXIST ON THE SUBJECT PROPERTY.

Viktor P. Meun LS 8682

TOAL ENGINEERING, INC.
Civil Engineers and Land Surveyors
139 Avenida Navarro, San Clemente, Calif. 92672
Ph: 949-492-8586 Fax: 949-498-8625

REVISIONS				BY	DATE	APVD.	DATE	DR. FILE	APVD.

TOPOGRAPHIC & BOUNDARY SURVEY
LOT 23, BLOCK 17, TRACT 793
259 WEST MARQUITA, SAN CLEMENTE, CALIFORNIA
PREPARED FOR CALPAC PROPERTIES, LLC


SHEET 1 OF 1
JOB NO. 15523

GEOLOGIC CHARTS

- | | |
|-------|---|
| Q1 | UNDESIRABLE DEFECTS |
| TRUFF | BLUFF TRUFF DEFECTS |
| ST | NON-TRUFF TRUFF DEFECTS |
| Q1M | MAJOR TRUFF DEFECTS |
| TC | CONCRETE FOUNDATION, CRACKS & SANDSTONE |

2. GEOLOGIC CHARACTER, approximate location. Quoted where location is uncertain or inferred.

3. HORIZONTAL CUP OF BECOMES RARE, PROJECTED IN
INSTEAD THE SURFACE WRAPPING
4. APPARENT CUP OF SHIRT RARE, PROJECTED OR
INWARD FROM SURFACE WRAPPING



SCALE: 1" = 20'


CROSS-SECTION A-A
259-261 WEST MARQUITA
SAN CLEMENTE, CALIFORNIA
7/1/2015 - CBC

SITE ADDRESS:
261 WEST MARQUITA,
SAN CLEMENTE, CALIFORNIA 92672


LEGAL DESCRIPTION:
261 WEST MARQUITA, LOT 24, BLOCK 17, TRACT 793

FIGURE 2-SECTION A-A

[illegible]



- EXPLANATION**
- QS LANDSLIDE DEBRIS
 - TAD BLUFF TAIL DEBRIS
 - SLT NON-HAZARDOUS TAIL DEBRIS DEPOSITS
 - QW HAZARDOUS TAIL DEBRIS DEPOSITS
 - TE BEDROCK FOUNDATION, SLOTTING & CRACKING



NOTE: The landslide configurations shown herein are based on information from surface mapping of topographic ground expressions and ground surface profiles plotted from that topography. Verification of the landslide limits and slide plane would require subsurface exploration.

SITE ADDRESS:
259 WEST MARQUITA,
SAN CLEMENTE, CALIFORNIA 92672

LEGAL DESCRIPTION:
259 WEST MARQUITA, LOT 23, BLOCK 17, TRACT 793



REVISION	DESCRIPTION	DATE	SCALE	DESIGNED	DRAWN	CHECKED	BENCHMARK	PLANS PREPARED BY:	ENGINEER & SURVEYOR, INC.	FIGURE 3-SECTION B-B'	1 OF 1 SHEETS
			N/A					PETER and ASSOCIATES	1515 GALE WALK, SAN CLEMENTE, CA 92672	261 WEST MARQUITA	
			AS20111116					WWW.PETERASSOCIATES.COM	1515 GALE WALK, SAN CLEMENTE, CA 92672	SAN CLEMENTE, CA 92672	
			15151116						TEL: (949) 492-2735 FAX: (949) 492-1881	PREPARED FOR: INM RANCH (259 WEST MARQUITA) & SEA BLUFF HOA (261 WEST MARQUITA)	


Exhibit 3 **Page 4 of 5**

EXPLANATION


- Qs** COLLUVIAL DEBRIS
- Qd** CLASTIC DEPOSITS
- Qm** FERTILIZED MARINE AND MARINE TERRACE DEPOSITS
- Tc** CAP STRAND FORMATION BEDROCK

GEOLOGIC CONTACT, queried where uncertain or inferred.

EXPLANATION: STRIKE SLIP AND DIP SLIP




LANDSLIDE NOMENCLATURE



B-2 EROSIONARY BORING AND SLOPE INCLINOMETER ASSOCIATED WITH THIS INVESTIGATION

B-2 / DH-1 EXPLORATORY BORING FROM PREVIOUS INVESTIGATION. SE = Bagani Engineering. PA = Paler and Associates, Inc.

GEOTECHNICAL SECTION LINE





2016



2017



2016



2017



2016



2017



2016



2017




2016



2017




Temp. Soldier Pile Wall Sketch



Reasonable Sol'n (not calculated or analyzed)

1. 8' of "I" beam above existing grade
2. 17' of "I" beam drilled (not driven) below existing grade
3. 24" drilled caisson, backfilled w/ concrete.
4. Either use wood lagging or steel plates.

not to scale



typical beam used for
temp shoring on other
projects






Photo from
8/3/2015

2/19/19



ⓧ Approx. Location of
Slope Inclinometer

City constructed
temporary wood lagging
wall beginning to be
overtopped



Photo from
May 2018

Exhibit 5

Page 7 of 9



Photo from
January 2019

Exhibit 5


Page 8 of 9



Photo from
January




Photo from
January 2019



CONSTRUCTION NOTES:
① RECONSTRUCT BLUFF PER CDMO STANDARD PLAN 1322 AND PER SOIL ENGINEER OF RECORD RECOMMENDATIONS

BLUFF AREA PERCENTAGES:

261 WEST MARQUITA	PERCENT:
257 WEST MARQUITA	23.3%
257 WEST MARQUITA	17%
257 WEST MARQUITA	100%






PLANS PREPARED BY: **PETER and ASSOCIATES** ENGINEERS & ARCHITECTS
1919 DUNE WALK, SAN CLEMENTE, CA 92672
TEL: (949) 495-5752 FAX: (949) 495-1891
WWW.PETERASSOC.COM

ROUGH GRADING PLAN 20 SCALE
259 WEST MARQUITA
SAN CLEMENTE, CA 92672
PREPARED FOR: TIM RACHO
SEA BLUFF HOA (261 WEST MARQUITA)




PREPARED BY OR UNDER DIRECTION OF:
STEPHEN B. PETER
DATE

REVISION	BY	DESCRIPTION	APPROVED	DATE	SCALE	DESIGNED	DRAWN	CHECKED	LEGAL DESCRIPTION	BENCHMARK	A.P. NUMBER	PLANS PREPARED BY:	ROUGH GRADING PLAN 20 SCALE	CITY ID
1	SP	RECEIVED BLUFF SLOPE TO PRE-SLOPE BLUFF SLOPE		3/10/18	N/A				LOT 23, BLOCK 17 TRACT 793	OCEAN 35S-2-82 ELEVATION = 9255.6 NAD 83 DATUM	692-055-07	PETER and ASSOCIATES ENGINEERS & ARCHITECTS 1919 DUNE WALK, SAN CLEMENTE, CA 92672 TEL: (949) 495-5752 FAX: (949) 495-1891 WWW.PETERASSOC.COM	259 WEST MARQUITA SAN CLEMENTE, CA 92672 PREPARED FOR: TIM RACHO SEA BLUFF HOA (261 WEST MARQUITA)	ENC 18
														C-3A



REGION	BY	DESCRIPTION	APPROVED	DATE	SCALE	DESIGNED	SCALE	ORIGIN	LEGAL DESCRIPTION	BENCHMARK	A.P. NUMBER	PETER and ASSOCIATES ENGINEERS	SECTIONS A,B,C
1	SP	RECORD BLUFF SLOPE TO PRE-SLOPE BLUFF SLOPE		3/15/18	N/A				LOT 23, BLOCK 17	CGSM 355-2-82 ELEVATION = 95.558 NAD 83/010M	692-095-07	1419 CALIF. ULS SAN CLEMENTE, CA 92073 Tel: (949) 469-3725 Fax: (949) 462-1891	259 WEST MARQUITA SAN CLEMENTE, CA 92072 PREPARED FOR: TIM RACCH SEA BLUFF HOA (261 WEST MARQUITA)

CITY ID
ENG 18-
PREPARED BY OR UNDER DIRECTION OF:
STEPHEN B. PETER
DATE
REGISTERED PROFESSIONAL ENGINEER
No. 38623
State of California
PETER and ASSOCIATES ENGINEERS






REASON	BY	DESCRIPTION	APPROVED	DATE	SCALE	DESIGNED	SEAL	CHECKED	DATE	LEGAL DESCRIPTION	BENCHMARK	A.P. NUMBER	ENGINEER'S & ASSOCIATES	SECTIONS D,E,F
1	SP	REMOVED BLUFF SLOPE TO PRE-SLOPE BLUFF SLOPE		3/19/18	N/A					LOT 23, BLOCK 17 TRACT 7933	05584 355-2-82 ELEVATION = 96358 NAVD 83/DATUM	692-095-07	PETER and ASSOCIATES ENGINEERS & ASSOCIATES	259 WEST MARQUITA SAN CLEMENTE, CA 92672 PREPARED FOR: TIM RACCH SEA BLUFF HOA (261 WEST MARQUITA)

CITY ID
ENG 18-
PREPARED BY OR UNDER DIRECTION OF:
STEPHEN B. PETER
DATE

REGISTERED PROFESSIONAL ENGINEER
No. 50012
Exp. 2024
STATE OF CALIF.

SEALED
10/09/2018





REVISION	BY	DESCRIPTION	APPROVED	DATE	SCALE	DESIGNED	GRADER	LEGAL DESCRIPTION	BENCHMARK	A.P. NUMBER	PROJECT	SECTION
1	SP	REVISION BLUFF SCALE TO PRE-SIDE BLUFF SCALE		5/7/18	N/A			LOT 23, BLOCK 17	OCSEA 35S-2-22 ELEVATION = 95.598 NAVD 85/DTM	692-095-07	259 WEST MARQUITA SAN CLEMENTE, CA 92672 PREPARED FOR: TIM RACH SEA BLUFF HOA (261 WEST MARQUITA)	C-6


CITY ID
END 18--

PREPARED BY OR UNDER DIRECTION OF:
STEPHEN B. PETER DATE

REGISTERED PROFESSIONAL ENGINEER
No. 38023
State of California

SECTIONS G,H,I
259 WEST MARQUITA
SAN CLEMENTE, CA 92672
PREPARED FOR: TIM RACH
SEA BLUFF HOA (261 WEST MARQUITA)

[illegible]



SIERRA SLOPE TYPICAL CROSS-SECTION
NOT TO SCALE

- NOTES:**
1. TOPSOIL SHALL BE LOAMY SAND OR FINER GRADATION WITH 10% - 15% ORGANIC CONTENT OR MATERIAL APPROVED BY A QUALIFIED LANDSCAPE ARCHITECT. VEGETATION TYPE SHALL BE SPECIFIED BY A QUALIFIED LANDSCAPE ARCHITECT. ALL PLANTING SHALL BE PLACED PRIOR TO PLACEMENT OF TURF REINFORCEMENT MAT.
 2. ALL SOIL PARAMETERS AND BUILDING LOAD WERE ASSUMED TO PERFORM THE PRELIMINARY DESIGN. ALL DESIGN PARAMETERS MUST BE VERIFIED PRIOR TO FINAL DESIGN.

THIS PRELIMINARY DRAWING, DESIGN NOTES AND ASSOCIATED CALCULATIONS HAVE BEEN PREPARED BY TENSAR INTERNATIONAL CORPORATION (A GEOTEC CORPORATION) FOR PRELIMINARY DESIGN PURPOSES ONLY AND SHALL NOT BE USED OR RELIED UPON FOR FINAL DESIGN OR CONSTRUCTION.

MARGUITA SLOPE REPAIR

THIS DESIGN IS BASED UPON SPECIFIC PROPERTIES OF THOSE SPECIFIC TENSAR PRODUCTS INCORPORATED HEREIN WHICH ARE PROPRIETARY TO TENSAR. TENSAR PRODUCTS ARE NOT TO BE USED FOR ANY OTHER PROJECT. THIS DESIGN, THIS DRAWING IS BEING FURNISHED FOR USE ON THIS SPECIFIC PROJECT ONLY. ANY PARTY ACCEPTING THIS DOCUMENT DOES SO IN FULL KNOWLEDGE AND UNDERSTANDING OF THE LIMITATIONS OF THIS DESIGN AND THIS DRAWING. TENSAR INTERNATIONAL CORPORATION SHALL NOT BE RESPONSIBLE FOR ANY PART NOT DISCLOSED TO OTHERS WITHOUT THE CONSENT OF TENSAR INTERNATIONAL CORPORATION.




© 2016, TENSAR INTERNATIONAL CORPORATION

REVISIONS			
NO.	DATE	DESCRIPTION	BY / NO.
1	06/20/16	ISSUED FOR REVIEW	JL
2			
3			

CLIENT		PETER AND ASSOCIATES, INC.	
		1819 CALLE VALLE	
		SAN CLEMENTE, CA 92672	
		(650) 832-0075	

PROJECT NAME		MARGUITA SLOPE REPAIR	
PROJECT LOCATION		SAN CLEMENTE	
STATE OR FEDERAL AID PROJECT NO.		CALIFORNIA	

SHEET TITLE			
TYPICAL CROSS-SECTION			
DRAWN BY	NAME	DATE	TOP PROJECT NO.
DESIGNED BY	JL	06/16/2016	AS SHOWN
CHECKED BY	JL	06/20/2016	SHEET 1 OF 3



TURF REINFORCEMENT INSTALLATION
NOT TO SCALE


THIS PRELIMINARY DRAWING, DESIGN NOTES AND ASSOCIATED CALCULATIONS HAVE BEEN PREPARED BY TENSAR INTERNATIONAL CORPORATION (A GEOTEC CORPORATION) FOR PRELIMINARY DESIGN PURPOSES ONLY AND SHALL NOT BE USED OR RELIED UPON FOR FINAL DESIGN OR CONSTRUCTION.

MARGUITA SLOPE REPAIR

THIS DESIGN IS BASED UPON SPECIFIC PROPERTIES OF THOSE SPECIFIC TENSAR PRODUCTS INCORPORATED HEREIN WHICH ARE PROPRIETARY TO TENSAR. ANY OTHER PRODUCT OR MATERIALS USED IN THIS DESIGN ARE SPECIFIC TO THIS PROJECT ONLY. ANY PARTY ACCEPTING THIS DOCUMENT DOES SO AT THEIR OWN RISK AND WITHOUT LIABILITY TO TENSAR. TENSAR SHALL NOT BE RESPONSIBLE FOR ANY DAMAGE OR LOSS OF ANY KIND, INCLUDING BUT NOT LIMITED TO, IN PART, NOT DISCLOSED TO OTHERS, WITHOUT THE CONSENT OF TENSAR INTERNATIONAL CORPORATION.

REVISONS		CLIENT		PROJECT NAME		SHEET TITLE	
NO.	DATE	DESCRIPTION	BY	NO.	DATE	DESCRIPTION	NO.
1	06/20/2016	ISSUED FOR REVIEW	JL	1	06/16/2016	DESIGNED BY	1
2				2	06/20/2016	CHECKED BY	2
3				3			3
4				4			4
5				5			5
6				6			6
7				7			7
8				8			8
9				9			9
10				10			10
11				11			11
12				12			12
13				13			13
14				14			14
15				15			15
16				16			16
17				17			17
18				18			18
19				19			19
20				20			20
21				21			21
22				22			22
23				23			23
24				24			24
25				25			25
26				26			26
27				27			27
28				28			28
29				29			29
30				30			30
31				31			31
32				32			32
33				33			33
34				34			34
35				35			35
36				36			36
37				37			37
38				38			38
39				39			39
40				40			40
41				41			41
42				42			42
43				43			43
44				44			44
45				45			45
46				46			46
47				47			47
48				48			48
49				49			49
50				50			50
51				51			51
52				52			52
53				53			53
54				54			54
55				55			55
56				56			56
57				57			57
58				58			58
59				59			59
60				60			60
61				61			61
62				62			62
63				63			63
64				64			64
65				65			65
66				66			66
67				67			67
68				68			68
69				69			69
70				70			70
71				71			71
72				72			72
73				73			73
74				74			74
75				75			75
76				76			76
77				77			77
78				78			78
79				79			79
80				80			80
81				81			81
82				82			82
83				83			83
84				84			84
85				85			85
86				86			86
87				87			87
88				88			88
89				89			89
90				90			90
91				91			91
92				92			92
93				93			93
94				94			94
95				95			95
96				96			96
97				97			97
98				98			98
99				99			99
100				100			100


CLIENT		PROJECT NAME		SHEET TITLE			
PETER AND ASSOCIATES, INC. 1819 CALLE VALE SAN CLEMENTE, CA 95072 (650) 832-0075		MARGUITA SLOPE REPAIR		TURF REINFORCEMENT DETAIL			
Tensar. <small>Tensar International Corporation 2500 Network Parkway, Suite 500 Redwood Group 95000 1705-4-0000</small>		PROJECT LOCATION SAN CLEMENTE STATE OF FEDERAL ID PROJECT No.		CALIFORNIA			
		DRAWN BY JLJ		NAME JLJ		DATE 06/16/2016	
		DESIGNED BY JLJ				SCALE AS SHOWN	
		CHECKED BY JLJ				SHEET 2 OF 3	



NOTE:
CONTRACTOR TO COORDINATE THE REQUIRED PAVEMENT SECTIONS WITH THE TOP OF THE SLOPE. THE GEORGRID SHOULD BE PLACED AT A MINIMUM OF 4" OF COVER BETWEEN THE TOP OF SUBGRADE AND THE GEORGRID.

PLACEMENT AT PAVEMENT SECTION-CROSS SECTION

NOT TO SCALE



GEOGRID PLACEMENT ON CURVES DETAIL-PLAN VIEW

NOT TO SCALE

THIS PRELIMINARY DRAWING, DESIGN NOTES AND ASSOCIATED CALCULATIONS HAVE BEEN PREPARED BY TENSAR INTERNATIONAL CORPORATION (A GEORGRID CORPORATION) FOR PRELIMINARY DESIGN PURPOSES ONLY AND SHALL NOT BE USED OR RELIED UPON FOR FINAL DESIGN OR CONSTRUCTION.

MARGUITA SLOPE REPAIR

THIS DESIGN IS BASED UPON SPECIFIC PROPERTIES OF THOSE SPECIFIC TENSAR PRODUCTS INCORPORATED HEREIN WHICH ARE PROPRIETARY TO TENSAR. ANY OTHER PRODUCT OR MATERIALS USED IN THIS DESIGN ARE NOT APPROVED BY TENSAR. ANY PARTY ACCEPTING THIS DOCUMENT DOES SO AT THEIR OWN RISK. TENSAR DISCLAIMS ANY AND ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. TENSAR SHALL NOT BE LIABLE FOR ANY AND ALL DAMAGES, INCLUDING BUT NOT LIMITED TO, CONSEQUENTIAL DAMAGES, ARISING OUT OF OR IN CONNECTION WITH THE USE OF THIS DOCUMENT. TENSAR SHALL NOT BE LIABLE FOR ANY AND ALL DAMAGES, INCLUDING BUT NOT LIMITED TO, CONSEQUENTIAL DAMAGES, ARISING OUT OF OR IN CONNECTION WITH THE USE OF THIS DOCUMENT.

© 2016, TENSAR INTERNATIONAL CORPORATION




REVISIONS			
NO.	DATE	DESCRIPTION	BY
1	06/20/2016	ISSUED FOR REVIEW	JL
2			
3			

CLIENT
PETER AND ASSOCIATES, INC.
1819 CALLE VALLE
SAN CLEMENTE, CA 92672
(951) 832-0075

PROJECT NAME
MARGUITA SLOPE REPAIR

PROJECT LOCATION
SAN CLEMENTE
STATE OF CALIFORNIA, AND PROJECT NO. CALIFORNIA

SHEET TITLE			
GEOGRID PLACEMENT DETAIL			
DESIGNED BY	DATE	THICKNESS	SCALE
JL	06/16/2016	AS SHOWN	
CHECKED BY	DATE	SHEET	OF
JL	06/20/2016	3	3



OWNER: MR. TIM RACH
259 WEST MARQUITA
SAN CLEMENTE, California 92672

**CIVIL ENGINEER:
GEOTECHNICAL ENGINEER
Land Surveyor:**

PETER AND ASSOCIATES, INC.
1619 CALLE VALLE
SAN CLEMENTE, CALIFORNIA 92672
949-482-3755 OFFICE 949-492-1691 FAX
GEOCHEMICAL ENGINEER
CONTACT PERSON: MR. LAM PHAM NGC
EMAIL: LAM@PETERASSOC.COM
CIVIL ENGINEER
CONTACT PERSON: MR. STEPHEN PETER, PE
EMAIL: STEVE@PETERASSOC.COM

PREPARED BY OR UNDER DIRECTION OF
STEPHEN B. PETER DATE



259 WEST MARQUITA
SAN CLEMENTE, CA 92672
PREPARED FOR: TIM RACICH
SEA BLUFF HOA (261 WEST MARQUITA)

C-10	STAGIN
------	--------

STATION	BR	SECTION/DESCRIPTION	APPROX	DATE	SCALE	DESIGNED	CHECKED	LEAD, DESCRIPTION	BENCHMARK
					N/A			LOT 24, BLOCK 17 TRACT 793	OCSEMA 555-2-82 ELEVATION = 95.558 NAVD 88 DATUM
					ASR PLT NO 1421315		DATE		
					PROJECT NO 1421315				

PLANS PREPARED BY:
PETER and ASSOCIATES
DICKENS
GEOLOGISTS &
SURVEYORS, INC.

WWW.PETERASSOC.COM
1519 COALE VILLE, SAN CLEMENTE, CA 92672
Tel: (949) 492-5735 Fax: (949) 492-1891

259 WEST MARQUITA NATIVE LANDSCAPE PLAN AND SPECIFICATIONS

This Native Landscape Plan and Specifications (Specifications) for the slope repair project at 259 West Marquita, City of San Clemente (City), California (Figure 1) provides guidelines for the installation and maintenance of native landscaping following completion of construction activities. The purpose of this revegetation effort is to provide self-sustaining, native vegetation within the slope repair portion of the project area that would be disturbed during project activities. This revegetation effort will potentially provide habitat (coastal bluff scrub) for native wildlife species. In addition, the construction staging area will be revegetated following construction activities.

These Specifications are designed to be a user-friendly document for use by all parties (the land owner, the monitor, and the Maintenance Contractor) associated with the revegetation effort. Additional technical documents (e.g., irrigation specifications) are not included at this planning stage but may be required in the future.

MONITORING AND MAINTENANCE

Restoration Monitor

The Restoration Monitor is the land owner's representative in the field and shall be responsible for monitoring the installation, establishment, and maintenance according to these Specifications. The duties of the Restoration Monitor shall include performing periodic assessments of the revegetation effort to identify any portions that need to be maintained, identify plant species that should be preserved or removed, and propose remedial measures if the revegetation effort is unsuccessful. The Restoration Monitor shall assess the revegetation area regularly during the revegetation effort to ensure that the establishment of desirable species is being promoted and that undesirable species are being removed. The Restoration Monitor shall assess the health of the plant community and degree of invasion by undesirable species. The Restoration Monitor shall prepare a brief field memorandum for each inspection that will be provided to the Maintenance Contractor and the land owner. The field memorandums will include observations relating to the health of the native plant material and degree of invasion by nonnative species, as well as recommended actions to be taken by the Maintenance Contractor to ensure the establishment of the installed vegetation.

Maintenance Contractor

The Maintenance Contractor responsible for the installation and maintenance of the revegetation effort shall be familiar with all aspects of the project, including equipment and materials being utilized. The Maintenance Contractor shall be familiar with the nonnative species that occur in the vicinity of the revegetation area, including, but not limited to, the list provided in Table A. The Maintenance Contractor shall also be familiar with all of the native species to be installed within the revegetation area (Tables B and C below). Following installation, the revegetation shall be maintained



LSA

LEGEND

- Approximate Native Landscaping Limits (~0.61 ac)
- Approximate City-directed Landscaping Limits (~0.19 ac)
- Construction Fence



SOURCE: Bing Maps (c. 2014); Peter and Associates (7/7/2018)
L:\DV\1601\GIS\ProjectLocation.mxd (7/7/2018)

FIGURE 1

259 West Marquita
Native Landscape Plan and Specifications
Project Location

Table A: Nonnative Species

Scientific Name	Common Name
<i>Acacia</i> sp.	acacia
<i>Bassia hyssopifolia</i>	five-hook bassia
<i>Carpobrotus edulis</i>	Hottentot-fig
<i>Crassula ovata</i>	jade plant
<i>Cynodon dactylon</i>	Bermuda grass
<i>Drosanthemum floribundum</i>	flowery ice plant
<i>Hedera helix</i>	English ivy
<i>Myoporum laetum</i>	myoporum

Table B: Slope Repair Container Plant List

Scientific Name	Common Name	Plants/Acre
<i>Artemisia californica</i>	coastal sagebrush	75
<i>Atriplex lentiformis</i>	Brewer's saltbush	100
<i>Eriogonum fasciculatum</i>	California buckwheat	75
<i>Lycium californicum</i>	California boxthorn	40
<i>Opuntia littoralis</i>	coastal prickly pear	300
<i>Opuntia prolifera</i>	coastal cholla	300
<i>Peritoma arborea</i>	bladderpod	25
<i>Rhus integrifolia</i>	lemonade berry	100

Table C: Slope Repair Seed List

Scientific Name	Common Name	Pounds/Acre
<i>Acmispon glaber</i>	coastal deerweed	3.0
<i>Ambrosia acanthicarpa</i>	sand-bur	3.0
<i>Artemisia californica</i>	coastal sagebrush	1.0
<i>Atriplex canescens</i>	fourwing saltbush	10.0
<i>Atriplex lentiformis</i> ssp. <i>breweri</i>	Brewer's salt bush	8.0
<i>Baccharis pilularis</i>	coyote bush	1.0
<i>Camissoniopsis cheiranthifolia</i>	beach evening primrose	0.5
<i>Cryptantha intermedia</i>	common cryptantha	3.0
<i>Distichlis spicata</i>	saltgrass	2.0
<i>Elymus condensatus</i>	giant wild-rye	2.0
<i>Encelia californica</i>	California encelia	6.0
<i>Eriogonum fasciculatum</i>	California buckwheat	15.0
<i>Eriogonum parvifolium</i>	bluff buckwheat	4.0
<i>Frankenia salina</i>	alkali heath	0.5
<i>Isocoma menziesii</i>	coastal goldenbush	4.0
<i>Lasthenia californica</i>	coastal goldfields	1.0
<i>Lupinus bicolor</i>	miniature lupine	5.0
<i>Melica imperfecta</i>	small-flowered melic grass	2.0
<i>Mimulus aurantiacus</i> var. <i>puniceus</i>	red bush monkeyflower	2.0
<i>Plantago erecta</i>	California plantain	4.0
<i>Rhus integrifolia</i>	lemonade berry	20.0
<i>Sisyrinchium bellum</i>	blue-eyed grass	1.0
<i>Stipa lepida</i>	foothill needlegrass	3.0
<i>Stipa pulchra</i>	purple needlegrass	6.0

regularly in accordance with these Specifications. Normal maintenance will include weeding, herbivore control (e.g., protective caging), trash cleanup, and watering as necessary. The site shall be maintained for nonnative species on a monthly basis for 2 years following installation to ensure the establishment of the installed vegetation. With the exception of those species that cannot be eradicated through manual removal, undesirable species present shall be removed manually. Herbicide usage shall be subject to approval by the Restoration Monitor.

SITE PREPARATION

Erosion Control

Erosion control measures shall be supplied, installed, and maintained as necessary to comply with applicable permit conditions and regulations. In the case of heavy rainfall conditions, nonvegetative erosion control measures (e.g., sandbags, rice straw wattles, or silt fence) may need to be installed. The Maintenance Contractor shall be responsible for all post-grading erosion control for the entire term of the contract. Erosion control shall include, but is not limited to: (1) continuation of nonvegetative erosion control, as necessary; and (2) repair of damaged plants, rutting, and washouts.

Irrigation

An irrigation system to be designed and built by the Maintenance Contractor will be installed to facilitate the establishment of the installed plant material. The Maintenance Contractor will be responsible for removal of the irrigation system once the installed plant material has become established.

INSTALLATION MATERIALS

The species to be installed within the slope repair portion of the project area were selected based on the native species found in the project vicinity and those species known to be components of healthy, native coastal bluff communities. The genetic source of all container plants and seed to be installed in this area will be within 20 miles of the project site. All species substitution decisions or alternative genetic sources shall be approved by the Restoration Monitor.

The construction staging area is currently vegetated with a mixed native and nonnative (ornamental) plant palette that was installed adjacent to the existing beach trail. This area was used as a construction staging area during the construction of the beach trail and was not restored to native habitat following completion of construction activities. This area will not be revegetated with a native plant palette following construction activities unless otherwise directed by the City. This area will be revegetated with a City of San Clemente-directed plant palette to be provided at a later date.

All container plants installed within the slope repair portion of the project area shall be installed within 3 days following acceptable delivery. All container plants shall be watered-in at the time of installation. The list of species and quantities per acre to be installed are presented in Table B. The container size for all plants is 1 gallon; however, cactus species may be installed as pads, if available.

The slope repair revegetation area will be hand-seeded or hydroseeded. The list of species to be seeded and the required pounds per acre of each species are presented in Table C. The amount of seed required is based on the pure live seed, percent purity, and percent germination data available at the time these Specifications were written. Prior to procurement of the seed, the Restoration Monitor shall obtain updated pure live seed, percent purity, and percent germination data from the seed supplier, and shall make any needed adjustments based on availability and cost considerations. Any adjustments shall be documented and reported to the appropriate agencies within an as-built report or other similar document.

Hand-Seeding/Broadcast Seeding


If hand-seeded, the specified seed mix will be mixed with bran at a 2:1 ratio by volume and will be broadcast over the specified area. After hand-seeding/broadcasting, the seed is to be lightly raked into the soil (but not buried) with a flexible landscape rake or equivalent.

Hydroseeding

If hydroseeded, a two-stage hydroseed application method shall be employed. Preventive measures must be taken to avoid damage to container plants or adjacent native vegetation (i.e., spraying and covering plants with mulch, breaking stems, or branches with hoses). The application procedure is as follows:

- **First Application**
 - 150 pounds per acre (lbs/ac) of 100 percent long-strand wood fiber (no tackifier)
 - Specified seed
- **Second Application**
 - 2,000 lbs/ac of 100 percent long-strand wood fiber (no tackifier)
 - 150 lbs/ac Ecology Control "M" binder

All hydroseed mixing shall be performed in a clean tank and shall take place at the project site. All hoses shall also be clean. The Maintenance Contractor shall spray designated areas with the slurry in a sweeping motion and in an arched stream until a uniform coat is achieved, with no slumping or shadowing, as the material is spread at the required rate. The tanks must be emptied completely during each stage of hydroseeding. Any slurry mixture that has not been applied by the Maintenance Contractor within 1 hour after mixing shall be rejected and replaced at the Maintenance Contractor's expense.



LOT SIZE = 20,879.2 SF
LOT SIZE = 0.48 ACRES
NO EX. EASEMENTS

SITE PLAN

SITE SECTION 1

KEYNOTES

- 1. ADJUST
- 2. ADJUST
- 3. ADJUST
- 4. ADJUST
- 5. ADJUST
- 6. ADJUST
- 7. ADJUST
- 8. ADJUST
- 9. ADJUST
- 10. ADJUST
- 11. ADJUST
- 12. ADJUST
- 13. ADJUST
- 14. ADJUST
- 15. ADJUST
- 16. ADJUST
- 17. ADJUST
- 18. ADJUST
- 19. ADJUST
- 20. ADJUST
- 21. ADJUST
- 22. ADJUST
- 23. ADJUST
- 24. ADJUST
- 25. ADJUST
- 26. ADJUST
- 27. ADJUST
- 28. ADJUST
- 29. ADJUST
- 30. ADJUST
- 31. ADJUST
- 32. ADJUST
- 33. ADJUST
- 34. ADJUST
- 35. ADJUST
- 36. ADJUST
- 37. ADJUST
- 38. ADJUST
- 39. ADJUST
- 40. ADJUST
- 41. ADJUST
- 42. ADJUST
- 43. ADJUST
- 44. ADJUST
- 45. ADJUST
- 46. ADJUST
- 47. ADJUST
- 48. ADJUST
- 49. ADJUST
- 50. ADJUST
- 51. ADJUST
- 52. ADJUST
- 53. ADJUST

MATERIALS

1. CONCRETE
2. CONCRETE
3. CONCRETE
4. CONCRETE
5. CONCRETE
6. CONCRETE
7. CONCRETE
8. CONCRETE
9. CONCRETE
10. CONCRETE
11. CONCRETE
12. CONCRETE
13. CONCRETE
14. CONCRETE
15. CONCRETE
16. CONCRETE
17. CONCRETE
18. CONCRETE
19. CONCRETE
20. CONCRETE
21. CONCRETE
22. CONCRETE
23. CONCRETE
24. CONCRETE
25. CONCRETE
26. CONCRETE
27. CONCRETE
28. CONCRETE
29. CONCRETE
30. CONCRETE
31. CONCRETE
32. CONCRETE
33. CONCRETE
34. CONCRETE
35. CONCRETE
36. CONCRETE
37. CONCRETE
38. CONCRETE
39. CONCRETE
40. CONCRETE
41. CONCRETE
42. CONCRETE
43. CONCRETE
44. CONCRETE
45. CONCRETE
46. CONCRETE
47. CONCRETE
48. CONCRETE
49. CONCRETE
50. CONCRETE
51. CONCRETE
52. CONCRETE
53. CONCRETE

GENERAL NOTES

Scale: 1/8" = 1'-0"

Sheet: 62/118

Project: A1.1



PROJECT X

259 WEST MARQUITA, SAN CLEMENTE

NOTES TO THE CONTRACTOR:

1. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE CITY OF SAN CLEMENTE AND THE CALIFORNIA DEPARTMENT OF WATER RESOURCES.

2. THE CONTRACTOR SHALL MAINTAIN ACCESS TO ALL ADJACENT PROPERTIES AT ALL TIMES.

3. THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTING ALL EXISTING UTILITIES AND STRUCTURES.

4. THE CONTRACTOR SHALL MAINTAIN ADEQUATE EROSION CONTROL MEASURES THROUGHOUT THE CONSTRUCTION PROCESS.

5. THE CONTRACTOR SHALL BE RESPONSIBLE FOR REMEDIATING ANY DAMAGE TO THE SITE OR ADJACENT PROPERTIES.

6. THE CONTRACTOR SHALL MAINTAIN ADEQUATE RECORDING OF ALL CONSTRUCTION ACTIVITIES.

7. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY INSURANCE COVERAGE.

8. THE CONTRACTOR SHALL MAINTAIN ADEQUATE SAFETY MEASURES ON THE SITE AT ALL TIMES.

9. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY APPROVALS FROM THE CITY OF SAN CLEMENTE.

10. THE CONTRACTOR SHALL MAINTAIN ADEQUATE RECORDING OF ALL CONSTRUCTION ACTIVITIES.


GENERAL NOTES	
1	PROPERTY LINE
2	ALL EXISTING BUILDING FOOTING AND STAY IN PLACE
3	FOUND. RETAINING
4	EXTERIOR
5	EXTERIOR
6	EXTERIOR RETAINING
7	EXTERIOR RETAINING
8	EXTERIOR RETAINING
9	EXTERIOR RETAINING
10	EXTERIOR RETAINING
11	EXTERIOR RETAINING
12	EXTERIOR RETAINING
13	EXTERIOR RETAINING
14	EXTERIOR RETAINING
15	EXTERIOR RETAINING
16	EXTERIOR RETAINING
17	EXTERIOR RETAINING
18	EXTERIOR RETAINING
19	EXTERIOR RETAINING
20	EXTERIOR RETAINING
21	EXTERIOR RETAINING
22	EXTERIOR RETAINING
23	EXTERIOR RETAINING
24	EXTERIOR RETAINING
25	EXTERIOR RETAINING
26	EXTERIOR RETAINING
27	EXTERIOR RETAINING
28	EXTERIOR RETAINING
29	EXTERIOR RETAINING
30	EXTERIOR RETAINING
31	EXTERIOR RETAINING
32	EXTERIOR RETAINING
33	EXTERIOR RETAINING
34	EXTERIOR RETAINING
35	EXTERIOR RETAINING
36	EXTERIOR RETAINING
37	EXTERIOR RETAINING
38	EXTERIOR RETAINING
39	EXTERIOR RETAINING
40	EXTERIOR RETAINING
41	EXTERIOR RETAINING
42	EXTERIOR RETAINING
43	EXTERIOR RETAINING
44	EXTERIOR RETAINING
45	EXTERIOR RETAINING
46	EXTERIOR RETAINING
47	EXTERIOR RETAINING
48	EXTERIOR RETAINING
49	EXTERIOR RETAINING
50	EXTERIOR RETAINING
51	EXTERIOR RETAINING
52	EXTERIOR RETAINING
53	EXTERIOR RETAINING
54	EXTERIOR RETAINING
55	EXTERIOR RETAINING
56	EXTERIOR RETAINING
57	EXTERIOR RETAINING
58	EXTERIOR RETAINING
59	EXTERIOR RETAINING
60	EXTERIOR RETAINING
61	EXTERIOR RETAINING
62	EXTERIOR RETAINING
63	EXTERIOR RETAINING
64	EXTERIOR RETAINING
65	EXTERIOR RETAINING
66	EXTERIOR RETAINING
67	EXTERIOR RETAINING
68	EXTERIOR RETAINING
69	EXTERIOR RETAINING
70	EXTERIOR RETAINING
71	EXTERIOR RETAINING
72	EXTERIOR RETAINING
73	EXTERIOR RETAINING
74	EXTERIOR RETAINING
75	EXTERIOR RETAINING
76	EXTERIOR RETAINING
77	EXTERIOR RETAINING
78	EXTERIOR RETAINING
79	EXTERIOR RETAINING
80	EXTERIOR RETAINING
81	EXTERIOR RETAINING
82	EXTERIOR RETAINING
83	EXTERIOR RETAINING
84	EXTERIOR RETAINING
85	EXTERIOR RETAINING
86	EXTERIOR RETAINING
87	EXTERIOR RETAINING
88	EXTERIOR RETAINING
89	EXTERIOR RETAINING
90	EXTERIOR RETAINING
91	EXTERIOR RETAINING
92	EXTERIOR RETAINING
93	EXTERIOR RETAINING
94	EXTERIOR RETAINING
95	EXTERIOR RETAINING
96	EXTERIOR RETAINING
97	EXTERIOR RETAINING
98	EXTERIOR RETAINING
99	EXTERIOR RETAINING
100	EXTERIOR RETAINING
101	EXTERIOR RETAINING
102	EXTERIOR RETAINING
103	EXTERIOR RETAINING
104	EXTERIOR RETAINING
105	EXTERIOR RETAINING
106	EXTERIOR RETAINING
107	EXTERIOR RETAINING
108	EXTERIOR RETAINING
109	EXTERIOR RETAINING
110	EXTERIOR RETAINING
111	EXTERIOR RETAINING
112	EXTERIOR RETAINING
113	EXTERIOR RETAINING
114	EXTERIOR RETAINING
115	EXTERIOR RETAINING
116	EXTERIOR RETAINING
117	EXTERIOR RETAINING
118	EXTERIOR RETAINING
119	EXTERIOR RETAINING
120	EXTERIOR RETAINING
121	EXTERIOR RETAINING
122	EXTERIOR RETAINING
123	EXTERIOR RETAINING
124	EXTERIOR RETAINING
125	EXTERIOR RETAINING
126	EXTERIOR RETAINING
127	EXTERIOR RETAINING
128	EXTERIOR RETAINING
129	EXTERIOR RETAINING
130	EXTERIOR RETAINING
131	EXTERIOR RETAINING
132	EXTERIOR RETAINING
133	EXTERIOR RETAINING
134	EXTERIOR RETAINING
135	EXTERIOR RETAINING
136	EXTERIOR RETAINING
137	EXTERIOR RETAINING
138	EXTERIOR RETAINING
139	EXTERIOR RETAINING
140	EXTERIOR RETAINING
141	EXTERIOR RETAINING
142	EXTERIOR RETAINING
143	EXTERIOR RETAINING
144	EXTERIOR RETAINING
145	EXTERIOR RETAINING
146	EXTERIOR RETAINING
147	EXTERIOR RETAINING
148	EXTERIOR RETAINING
149	EXTERIOR RETAINING



- ## KEYNOTES



ASH	ASHNET
CAR	CHERRY
COGN	CORNER FLOORING
GL-1	TRANSPARENT GLASS
GL-2	THICKENED GLASS/CLAY GLASS
GL-3	SEMI TRANSLUCENT GLASS
GRAY	GRAY, BROWN
ML-1	BRAID METAL, WOODEN BOI
ML-2	CUSTOM STAINLESS STEEL
STN-1	STONE FLOORING / ROCK / IN
STN-2	STONE WALL CAROLING
T-8	INTERIORLY COLORED BRICK
VEG	VEGETATION/PLANTING
WO-1	WOOD FLOORING
WO-2	WOOD SIDING
WO-3	WOOD SCREEN / FINISHING
WTR	WATER


DEMO PLAN



	First Floor	Habitable SF	SF
Total Deck	101	476.7	
Total Habitable	102	245.1	
Total Garage	103	244.57	
	104	244.57	
	104	2,369.17	
Total	2,369.17		
Second Floor			
Second Floor Habitable SF			
Total Deck	201	476.7	
Total Habitable	202	62.8	
Total Garage	203	62.8	
	204	1,892.4	
	205	26.0	
Total	206	12.0	
Total	2,448.9		
Second Floor Garage			
Total	211	966.0	
Second Floor Deck			
Total	221	256.4	
Total	222	250.9	
Total	223	250.9	
Total	224	509.0	
Third Floor			
Third Floor Habitable			
Total Deck	301	476.7	
Total Habitable	302	15.5	
Total Garage	303	138.7	
	304	298.2	
	305	62.3	
	306	551.7	
	307	507.0	
	308	945.0	
Total	3,592.2		
Third Floor Deck			
Total Deck	311	256.4	
Total Habitable	312	212.8	
Total Garage	313	NOT USED	
	314	NOT USED	
	315	169.5	
	316	143.0	
Total	781.7		
Roof Deck			
Total Deck	401	501.5	
Total Habitable	402	188.5	
Total Garage	403	435.0	
Total	1,125.0		
Roof Mesh			
Total Deck	404	162.0	
Total Habitable	405	162.0	
Total Garage	406	162.0	
Total	486.0		

[illegible]

DATE 1/8-1-0 06.18.2018			<h1 style="margin: 0;">PROJECT X</h1> <p style="margin: 0;">259 WEST MARQUITA, SAN CLEMENTE</p>
-------------------------------	---	---	---



KEYNOTES

- | ITEM | DESCRIPTION | UNIT | QUANTITY | REMARKS |
|------|---|------|----------|---------|
| 1 | PROPERTY LINE | | | |
| 2 | MAX ALLOWABLE BUILDING HEIGHT AND 20' AS NO | | | |
| 3 | ADJACENT NETWORK | | | |
| 4 | ADJACENT STREET | | | |
| 5 | ADJUTANT | | | |
| 6 | ADJUTANT | | | |
| 7 | ADJUTANT | | | |
| 8 | ADJUTANT | | | |
| 9 | ADJUTANT | | | |
| 10 | ADJUTANT | | | |
| 11 | ADJUTANT | | | |
| 12 | ADJUTANT | | | |
| 13 | ADJUTANT | | | |
| 14 | ADJUTANT | | | |
| 15 | ADJUTANT | | | |
| 16 | ADJUTANT | | | |
| 17 | ADJUTANT | | | |
| 18 | ADJUTANT | | | |
| 19 | ADJUTANT | | | |
| 20 | ADJUTANT | | | |
| 21 | ADJUTANT | | | |
| 22 | ADJUTANT | | | |
| 23 | ADJUTANT | | | |
| 24 | ADJUTANT | | | |
| 25 | ADJUTANT | | | |
| 26 | ADJUTANT | | | |
| 27 | ADJUTANT | | | |
| 28 | ADJUTANT | | | |
| 29 | ADJUTANT | | | |
| 30 | ADJUTANT | | | |
| 31 | ADJUTANT | | | |
| 32 | ADJUTANT | | | |
| 33 | ADJUTANT | | | |
| 34 | ADJUTANT | | | |
| 35 | ADJUTANT | | | |
| 36 | ADJUTANT | | | |
| 37 | ADJUTANT | | | |
| 38 | ADJUTANT | | | |
| 39 | ADJUTANT | | | |
| 40 | ADJUTANT | | | |
| 41 | ADJUTANT | | | |
| 42 | ADJUTANT | | | |
| 43 | ADJUTANT | | | |
| 44 | ADJUTANT | | | |
| 45 | ADJUTANT | | | |
| 46 | ADJUTANT | | | |
| 47 | ADJUTANT | | | |
| 48 | ADJUTANT | | | |
| 49 | ADJUTANT | | | |
| 50 | ADJUTANT | | | |
| 51 | ADJUTANT | | | |
| 52 | ADJUTANT | | | |
| 53 | ADJUTANT | | | |
| 54 | ADJUTANT | | | |
| 55 | ADJUTANT | | | |
| 56 | ADJUTANT | | | |
| 57 | ADJUTANT | | | |
| 58 | ADJUTANT | | | |
| 59 | ADJUTANT | | | |
| 60 | ADJUTANT | | | |
| 61 | ADJUTANT | | | |
| 62 | ADJUTANT | | | |
| 63 | ADJUTANT | | | |
| 64 | ADJUTANT | | | |
| 65 | ADJUTANT | | | |
| 66 | ADJUTANT | | | |
| 67 | ADJUTANT | | | |
| 68 | ADJUTANT | | | |
| 69 | ADJUTANT | | | |
| 70 | ADJUTANT | | | |
| 71 | ADJUTANT | | | |
| 72 | ADJUTANT | | | |
| 73 | ADJUTANT | | | |
| 74 | ADJUTANT | | | |
| 75 | ADJUTANT | | | |
| 76 | ADJUTANT | | | |
| 77 | ADJUTANT | | | |
| 78 | ADJUTANT | | | |
| 79 | ADJUTANT | | | |
| 80 | ADJUTANT | | | |
| 81 | ADJUTANT | | | |
| 82 | ADJUTANT | | | |
| 83 | ADJUTANT | | | |
| 84 | ADJUTANT | | | |
| 85 | ADJUTANT | | | |
| 86 | ADJUTANT | | | |
| 87 | ADJUTANT | | | |
| 88 | ADJUTANT | | | |
| 89 | ADJUTANT | | | |
| 90 | ADJUTANT | | | |
| 91 | ADJUTANT | | | |
| 92 | ADJUTANT | | | |
| 93 | ADJUTANT | | | |
| 94 | ADJUTANT | | | |
| 95 | ADJUTANT | | | |
| 96 | ADJUTANT | | | |
| 97 | ADJUTANT | | | |
| 98 | ADJUTANT | | | |
| 99 | ADJUTANT | | | |
| 100 | ADJUTANT | | | |

MATERIALS

- [illegible]

LEVEL 1 FLOOR PLAN


PROJECT X
259 WEST MARQUITA, SAN CLEMENTE


A2.1

1/4" = 1'-0"

06.18.2018

1990s, indicating a significant increase in the number of people who are using the Internet. This is a significant finding, as it suggests that the Internet is becoming a more important part of people's lives, and that it is being used for a wider range of purposes than just email and web browsing. This is a significant finding, as it suggests that the Internet is becoming a more important part of people's lives, and that it is being used for a wider range of purposes than just email and web browsing.





KEYNOTES

MATERIALS

ROOF PLAN


PROJECT X
259 WEST MARQUITA, SAN CLEMENTE

1/4" = 1'-0"

06.18.2018

A2.4






NORTH ELEVATION


[illegible]

A3.1





SECTION AA



SECTION BB

- [illegible]

KEYNOTES


[illegible]

MATERIALS

	PROPOSED BEAM WALL
	PROPOSED STUD WALL
	PROPOSED LOW WALL
	SITE WALL/MASONRY - REF. POINT A
	PROPOSED CONCRETE WALL



J. MARQUITA
TRACT NO. 793
M. 24/1-5



REGION	BY	DESCRIPTION	APPROVED	DATE	SCALE	DESIGNED	DRAWN	CHECKED	LEGAL DESCRIPTION	BENCHMARK	A.P. NUMBER	PREPARED FOR	DATE
1	SP	GRADED BLUFF SLOPE TO THE BLUFF SLOPE		5/10/16	N/A				LOT 23, BLOCK 17 TRACT NO. 793	OSMA, NS-2-22 ELEVATION 100.00 MAD 89/201M	692-095-07	PETER and ASSOCIATES ENGINEERS & ARCHITECTS, INC. 1515 OULE WALK, SAN CLEMENTE, CA 92672 Tel: (949) 482-3705 Fax: (949) 482-1881	SEA BLUFF HOK (261 WEST MARQUITA)

CITY ID
NO. 10-
PREPARED BY OR UNDER DIRECTION OF:
STEPHEN B. PETER
DATE

REGISTERED PROFESSIONAL ENGINEER
No. 58023
Exp. 12/31/17
STATE OF CALIFORNIA

[illegible]

Exhibit 12
Page 1 of 6

259 WEST MARQUITA - LEVEL 1

SCALE: 1/8" = 1'-0"

NOTE:
-THE HEIGHT DOES NOT EXCEED 25 FEET FROM AVERAGE ORIGINAL GRADE TO TOP-OF-ROOF, AS REQUIRED IN THE LUP.
-CANTILEVERED BUILDING ELEMENTS DO NOT EXTEND MORE THAN 10' INTO BLUFF SETBACK AS REQUIRED IN LUP POLICY HAZ-41.
-ZONE'S 15' FRONT SETBACK REDUCED TO 5' TO AVOID A TAKING AS ALLOWED IN LUP POLICY HAZ 41.

LEGEND:

- PREVIOUSLY PROPOSED BLUFF EDGE (Blue dashed line)
- NEW PROPOSED BLUFF EDGE (Green dashed line)
- EXISTING BLUFF EDGE (Red dashed line)
- NEW PROPOSED 10' DECK SETBACK (Red dashed line)
- PREVIOUSLY PROPOSED 25' BLUFF EDGE SETBACK (Green dashed line)
- NEW PROPOSED 25' BLUFF EDGE SETBACK (Blue dashed line)
- EXISTING 25' BLUFF EDGE SETBACK (Black dashed line)

Labels on plan:

- BLUFF SETBACK 25'
- NEW PROPOSED 25' BLUFF EDGE SETBACK
- EXISTING BLUFF EDGE
- NEW PROPOSED BLUFF EDGE
- EXISTING 25' BLUFF EDGE SETBACK
- 5' F.Y.S.B.
- DECK STRINGLINE
- BUILDING STRINGLINE
- BLUFF SETBACK 25'
- EXISTING 25' BLUFF EDGE SETBACK
- NEW PROPOSED 25' BLUFF EDGE SETBACK
- PREVIOUSLY PROPOSED 25' BLUFF EDGE SETBACK
- EXISTING BLUFF EDGE
- NEW PROPOSED BLUFF EDGE
- PREVIOUSLY PROPOSED BLUFF EDGE

[illegible]

Exhibit 12
Page 1 of 6

The site plan illustrates a building footprint with various setbacks and stringlines. The building includes rooms labeled 'Water closet', 'Lobby', 'Elevator', and 'Stair'. A 'Deck Stringline' and 'Building Stringline' are shown as dashed lines. The plan also features contour lines indicating elevation changes. Key setbacks include a '25' Bluff Edge Setback' and a 'New Proposed 25' Bluff Edge Setback'. A '5' F.Y.S.B.' (Front Yard Setback) is indicated near the bottom right.

Legend:

- PREVIOUSLY PROPOSED BLUFF EDGE (Blue dashed line)
- NEW PROPOSED BLUFF EDGE (Green dashed line)
- EXISTING BLUFF EDGE (Red dashed line)
- NEW PROPOSED 10' DECK SETBACK (Black dashed line)
- PREVIOUSLY PROPOSED 25' BLUFF EDGE SETBACK (Black solid line)
- NEW PROPOSED 25' BLUFF EDGE SETBACK (Green solid line)
- EXISTING 25' BLUFF EDGE SETBACK (Red solid line)

Labels:

- BLUFF SETBACK 25'
- NEW PROPOSED 25' BLUFF EDGE SETBACK
- EXISTING BLUFF EDGE
- NEW PROPOSED BLUFF EDGE
- DECK STRINGLINE
- BUILDING STRINGLINE
- 5' F.Y.S.B.

NOTE:
- THE HEIGHT DOES NOT EXCEED 25 FEET FROM AVERAGE ORIGINAL GRADE TO TOP-OF-ROOF, AS REQUIRED IN THE LUP.
- CANTILEVERED BUILDING ELEMENTS DO NOT EXTEND MORE THAN 10' INTO BLUFF SETBACK AS REQUIRED IN LUP POLICY HAZ-41.
- ZONE'S 15' FRONT SETBACK REDUCED TO 5' TO AVOID A TAKING AS ALLOWED IN LUP POLICY HAZ 41.

259 WEST MARQUITA - LEVEL 1

SCALE: 1/8" = 1'-0"

Exhibit 12
Page 1 of 6

- PREVIOUSLY PROPOSED BLUFF EDGE ————
- NEW PROPOSED BLUFF EDGE —————
- EXISTING BLUFF EDGE - - - - -
- NEW PROPOSED 10' DECK SETBACK - - - - -
- PREVIOUSLY PROPOSED 25' BLUFF EDGE SETBACK ————
- NEW PROPOSED 25' BLUFF EDGE SETBACK —————
- EXISTING 25' BLUFF EDGE SETBACK - - - - -
- 5' F.Y.S.B.
- BLUFF SETBACK
- DECK STRINGLINE
- BUILDING STRINGLINE
- 25'
- BLUFF SETBACK
- EXISTING 25' BLUFF EDGE SETBACK
- NEW PROPOSED 25' BLUFF EDGE SETBACK
- NEW PROPOSED 10' DECK SETBACK
- EXISTING BLUFF EDGE
- NEW PROPOSED BLUFF EDGE
- PREVIOUSLY PROPOSED BLUFF EDGE

NOTE:
- THE HEIGHT DOES NOT EXCEED 25 FEET FROM AVERAGE ORIGINAL GRADE TO TOP-OF-ROOF, AS REQUIRED IN THE LUP.
- CANTILEVERED BUILDING ELEMENTS DO NOT EXTEND MORE THAN 10' INTO BLUFF SETBACK AS REQUIRED IN LUP POLICY HAZ-41.
- ZONE'S 15' FRONT SETBACK REDUCED TO 5' TO AVOID A TAKING AS ALLOWED IN LUP POLICY HAZ 41.

259 WEST MARQUITA – LEVEL 1

SCALE: 1/8" = 1'-0"

Exhibit 12
Page 2 of 6



NOTE: THE HEIGHT DOES NOT EXCEED 25 FEET FROM AVERAGE ORIGINAL GRADE TO TOP-OF-ROOF, AS REQUIRED IN THE LUP CANTILEVERED BUILDING ELEMENTS DO NOT EXTEND MORE THAN 10' INTO BLUFF SETBACK AS REQUIRED IN LUP POLICY HAZ-41.
ZONE 5 IS FRONT SETBACK REDUCED TO 5' TO AVOID A TAKING AS ALLOWED IN LUP POLICY HAZ 41.


Exhibit 12
Page 3 of 6



NOTE: THE HEIGHT DOES NOT EXCEED 25 FEET FROM AVERAGE ORIGINAL GRADE TO TOP-OF-ROOF, AS REQUIRED IN THE LUP CANTILEVERED BUILDING ELEMENTS DO NOT EXTEND MORE THAN 10' INTO BLUFF SETBACK AS REQUIRED IN LUP POLICY HAZ-41.

ZONING S 15 FRONT SETBACK REDUCED TO 5' TO AVOID A TAKEAS AS ALLOWED IN LUP POLICY HAZ 41.

Exhibit 12
Page 4 of 6



259 WEST MARQUITA – LEVEL 4

SCALE: 1/8" = 1'-0"

Exhibit 12
Page 5 of 6

