CALIFORNIA COASTAL COMMISSION

South Coast Area Office 301 East Ocean Blvd., Suite 300 Long Beach, CA 90802 (562) 590-5071



W14e

5-19-1036 (Blue Lagoon Community Association) JULY 8, 2020

EXHIBITS

Table of Contents

Exhibit 1 – Vicinity Map

Exhibit 2 - Project Plans

Exhibit 3 - Site Photos

Exhibit 4 – Proposed Shotcrete Breccia Finish

Exhibit 5 - Location of Condo Units Relative to Bluff



5-19-1036 Blue Lagoon Vicinity Map Exhibit 1a



Blue Lagoon Condominium Complex Shown in Yellow

> 5-19-1036 Blue Lagoon Vicinity Map Exhibit 1b




REPAIR PLANS SLOPE STABILIZATION

FOR

BLUE LAGOON COMMUNITY ASSOCIATION LAGUNA BEACH, CALIFORNIA

MARCH 14, 2019



VICINITY MAP

SHEET INDEX

- C-1 TITLE SHEET
- C-2 EXISTING CONDITION
- C-3 PROPOSED REPAIR




SCOPE OF WORK

- THE REPAIR OF A SLOPE FAILURE LOCATED WITHIN THE BLUE LAGOON COMMUNITY CONSISTS OF:
- CONSTRUCTION OF A 15" (HICK MATURALIZED SHOTCKETE SORFIAZE, TO COVER 1,266 SQUARE PEET O THE EXISTING SLOPE, CARVED AND COLORED (BRECCIA-STYLE) TO MATCH SURROUNDING BLUFFS;
- REPAIR TO INCORPORATE AN UPPER AND LOWER BROW DITCH, AND A 6" DIAMETER DRAWINGE PIPE
- CONSTRUCTION OF A 3-FOOT HIGH. 12-FOOT LONG RETAINING WALL AT TOE OF SLOPE
- INSTALLATION OF NATIVE AND VERY LOW WATER USE PLANTINGS FOR SLOPE STABILIZATION.
- EXPERING REVISATION IS TO REMAIN




Blue Lagoon Slope Repair Project Plans Exhibit 2a







Blue Lagoon Slope Repair Project Plans Exhibit 2b



Blue Lagoon Slope Repair Project Plans Exhibit 2c



Blue Lagoon Slope Repair Project Plans Exhibit 2d



Blue Lagoon Slope Repair Site Photos Exhibit 3a





(Slope Conditions below Units 76 to 83; Source: ViaGeos 2017)


Blue Lagoon Slope Repair Site Photos Exhibit 3b



BRECCIA FORMATION EXAMPLE



Blue Lagoon Slope Repair Proposed Shotcrete Breccia Finish Exhibit 4



Blue Lagoon Exhibit 5

5-19-1036

Relative Locations of Condos and Slide Area